

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Tsuyoshi ISHIKAWA et al.

Application No.: 09/977,241

Confirmation No.: 2239

Filed: October 16, 2001

U.S. Patent No.: RE40,146

Issued: March 11, 2008



ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

For: TAPERED LIGHT GUIDE PLATE FOR SURFACE LIGHT SOURCE DEVICE AND
METHOD OF MAKING BY INJECTION MOLDING VIA SUPPLEMENTARY CAVITY

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

MAY 22 2008
of Correction

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: 5/20/08

By: Richard A. Gollhofer
Richard A. Gollhofer
Registration No. 31,106

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

RECEIVED-USPTO
Patent Publication

MAY 23 2008

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : RE40,146

DATED : March 11, 2008

INVENTOR(S) : Tsuyoshi ISHIKAWA et al.

Column 2, Line 20, change "space" to --shape--.

Column 5, Line 51, change "opposed" to --proposed--.

Column 6, Lines 24-25, change "parallelization" to --parallelization--.

Column 6, Line 44, change "had" to --has--.

Column 6, Line 51, change "place" to --plane--.

Column 7, Line 62, change "place" to --plane--.

Column 9, Line 44, change "end" to --ends--.

Column 9, Line 65, change "portions" to --positions--.

Column 11, Line 36, change "distinct" to --distant--.

Column 12, Line 58, change "plate" to --plane--

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. RE40,146

No. of add'l copies
@ 50¢ per page

C. M. 200

MAY 23 2003